


# BIG BOX

## Omnivore Euthanizer

### Users manual



# SETUP

Recommend	
Gas Fill Time	4-5 Minutes
Wait Time	4-5 Minutes
Gas Pressure	30-40 PSI

# OPERATION

1. Close the Unloading door and open the 2 Loading doors
2. Add cull birds and close Loading doors
3. Connect CO2 Cylinder
4. With a Timer counting, Open cylinder valve
5. After your timer is done close cylinder valve
6. Set another timer for your wait time
7. After your wait timer is done, open the unloading door and unload your culled birds

***ALWAYS operate in a well ventilated area.***

***ALWAYS operate in a space above 18°C(64°F)  
In a Warm Barn is ideal.***

***NEVER use the box for storage.***

***NEVER put anything but cull birds in Box***